



MAGICFLEX



PUFFED
POLYURETHANE



N°1 : 160°C
N°2 : 160°C



PEEL : HOT



Flex Blade 45°
Medium Pressure



PUFF



N°1 : 10SEC
N°2 : 30 SEC

SPECIFICATIONS

APPLICATION

1. Cut the material in right-reading with a Flex blade
2. Weed the excess material
3. Use a low tack application tape to transfer the material
4. Heat pressing on a SEFA machine in two steps:
1st : position and heat press the heat transfer on the garment protected by a silicon paper at 160°C - 10 sec - at the lowest pressure. Remove the application tape immediately after heat pressing.
2nd : heat pressing without application tape at 160°C - 30sec- at the lowest pressure.

THICKNESS:



Viscose Flok

White 1201 is printable

CARRIER: Adhesive & Transparent polyester



APPLIES ON

Cotton • Polyester • Acrylic & Similar Fibres

CARE & MAINTENANCE

- Always respect the garment's instructions
- Allow 24 hours after application before washing
- Iron the backside only

WASH

- Max 40° C
- Preferably inside out
- Do not bleach
- Tumble-dry unapproved
- Dry-cleaning unapproved

STORE

- Up to 1 year
- In a dry room (15-30° C)
- Away from sunlight
- In vertical position

Chemica
Heat transfers for textiles

NOTE: For best results, it is recommended to TEST prior to starting standard production